

### IRS Upright Identification

Ford recalled the IRS rear spindles in 1999 Mustang Cobras due to issues arising from the design of the cross-axis joints. All post-1999 Mustangs equipped with an IRS have the new style rear spindles. All of the older style rear spindles should have been replaced in the recall, but there still may be some floating around. The following comparison photos should help you identify what rear spindles you have.

*Note: The MMIRSB-3 IRS Cross-Axis Replacement Joints are only compatible with the new style rear spindles*



#### Recalled 1999 Cobra Rear Spindle



#### Revised 1999+ Cobra Rear Spindle

